



FIG. 1
Prior Art



SCANNED, # 12






FIG 2A






FIG 2B

1-14.3

FIG 4














FIG. 7 MEMORY BOARD 1801







$$\underline{\underline{220}}$$





F-14 RB


FIG. 9







[illegible]

5010,















FIG. 17

M5 INPUTS	M5 OUTPUT	M6 OUTPUT	M4 OUTPUT
0 0 0	0	0	0
0 0 1	0	0	0
0 1 0	0	0	0
0 1 1	1	0	0
1 0 0	0	1	0
1 0 1	1	1	0
1 1 0	1	1	1
1 1 1	1	1	1





164
 20